

1 SETUP

A EXTEND LEGS



Release latches and pull tripod legs out by sliding downward






B JOIN TOP & BASE



Insert tripod top into base and lock latches






G LEVEL BASE



The tripod legs are independently adjustable for uneven surfaces, and the base has a bubble level to assist with alignment before loading equipment.

NOTE: When possible, secure legs with sandbags.




2 TITAN MOUNTS

MOUNT POWER SUPPLY BRACKETS (X2)

NOTE: All mounting hooks hang downwards.




Align mount to the **Titan Cable** side (NOT the AC power plug side)




Use the **3mm T-Handle hex key** to secure fasteners into the mount holes

B MOUNT TITAN BRACKETS (X2)



Align mount to the **upper row** of holes



Use the 5mm T-Handle hex key to tighten fasteners into the mount holes